

The Warner Aircraft Corp.  
20263 Hoover Ave.  
Detroit, Mich.

Service Letter A-6

Sept. 7, 1939

Gentlemen:

Please be advised that PN 7741 valve spring-Inner, supersedes PN 7131 valve spring-Inner, on all super-scarab, scarab and scarab, Jr. engines.

When installing PN 7741 valve spring the end with the dampener coil marked in RED PAINT should be installed to rest on the No. 7094, valve washer, lower which bears on the cylinder head.

Very truly yours,

The Warner Aircraft Corp.