

THE WARNER AIRCRAFT CORPORATION
DETROIT MICHIGAN

SERVICE LETTER M-17

July 25, 1939

Gentlemen:

It has been brought to our attention that on some Super Scarab Model 165 installations suitable spacers have not been provided to give proper clearance between engine mounting ring and induction housing.


We are enclosing our Drawing No. SK-445 showing proper clearance between induction housing and engine mount ring.

Will you please check your engine installation and provide clearance as shown on Drawing No. SK-445.

Thanking you for your cooperation, we remain

Yours very truly,

THE WARNER AIRCRAFT CORPORATION



L. A. FAUNCE, Vice-President,
Sales Manager

LAF:DEC
BS