

THE WARNER AIRCRAFT CORPORATION
DETROIT MICHIGAN

SERVICE LETTER M-19

April 5, 1940

Gentlemen:


In the past when the steel ring which is attached to Part No. 7252, Thrust Bearing Cover, had become worn, it was necessary to replace the entire assembly.

It is now possible for us to install new rings in the old covers, and if in the future you will return to us part No. 7252, we can forward you a replacement part No. 7252 at a list price of \$4.33; this subject to a 20 per cent discount.

This new policy will be a considerable saving for your customer. The worn part No. 7252 should be returned to us, transportation charges prepaid.

Yours very truly,

THE WARNER AIRCRAFT CORPORATION



L. A. FAUNCE, Vice-President
Sales Manager

LAF:NC
DEC